

SECRET

SECRET 132041Z

OUT52456 25X1

1. CAMERA B 7 WAS USED IN MISSION 3791 FLOWN ON 11 DECEMBER 1963; PROCESSING WAS ACCOMPLISHED BY NAVY PIC.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD AND IN A FEW INSTANCES VERY GOOD.

B. 9R SIDE: A PLUS DENSITY EMULSION SCRATCH 0.2" FROM AND PARALLEL TO THE INBOARD EDGE IS PRESENT ON FRAMES 847 TO 931. FRAME 631 CONTAINS A MANUFACTURER'S SPLICE WHILE HEAT SPLICES WITH ASSOCIATED WRINKLES APPEAR ON FRAMES 649 AND 1314. NUMEROUS EMULSION GOUGES APPEAR ON FRAME 665. FOREIGN MATTER WAS NOTED ON FRAME 46.

C. 9L SIDE: OUTBOARD EDGE STATIC AND INBOARD EDGE FOG ARE PRESENT THROUGHOUT THE ENTIRE MISSION. POSITION INDICATOR LIGHTS WORK ERRATICALLY INTERMITTENTLY FROM HEAD TO TAIL. A COMET SHAPED MINUS DENSITY SPOT OCCURS ON FRAME 228. FRAME 132 CONTAINS A TAPE REPAIRED TEAR. A MANUFACTURER'S SPLICE IN FRAME 325 IS THE CAUSE OF A MINUS DENSITY STREAK 0.1" FROM THE INBOARD EDGE ON FRAME 322 TO 324.

D. BOTH SIDES: MINOR PROCESSING STREAKS ARE PRESENT FROM HEAD TO TAIL. THE METERING IS SLIGHTLY ERRATIC. THERE ARE 2104 TITLED FRAMES ON EACH SIDE OF THE MISSION.

E. THERE WERE NO MAJOR PROCESSING ANOMALIES IN THIS MISSION.

3. POSITIVE:

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING WERE GOOD.

Declassification Review by NGA/DoD

SECRET

GROUP 1  
Excluded from automatic  
downgrading and  
declassification

C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 20 PERCENT OF THIS MISSION.

4. NOTE: MISSION 3787, FLIGHT DATE 4 DECEMBER 1963, WAS INADVERTENTLY DESIGNATED MISSION 3784 IN THE EVALUATION REPORT. RECIPIENTS OF SUBJECT REPORT ARE REQUESTED TO CORRECT THEIR COPIES TO READ MISSION 3787.

S E C R E T

END OF MESSAGE

1